



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 01/8/2016
Facility name: North Regional Wastewater Authority
Ohio NPDES permit no.: IPD00020*JD
Period covered by report: 01/01/15 - 12/31/15

Contact person

Name: Joseph Hart
Title: Plant Manager
Mailing address: 3777 Old Needmore Road
Dayton, Ohio 45424
Telephone: (937)233 - 7083
Email: joseph.hart@veolia.com

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name Joseph Hart
(typed):

Title: Plant Manager II

Signature:

Date:

1/8/2016

Enter narrative analysis of WIB patterns by location, frequency and cause.

Tipp City:106 E. Main, grease in sewer main.

Huber Heights: No additional comments

Vandalia: Na